B.R No . 335

Date:31.08.2013

Inspection report for the Work of : Improvements of Drains at bagalagunte Main road Left Side in Ward No 14, Daasrahalli Sub Div

By.Sri.Muniyappa G M

Retd.Executive Engineer

Name of Work: Improvements of Drains at bagalagunte Main road Left Side in Ward No 14, Daasrahalli Sub Div

B.R.No 335, 31.08.2013

Estimated Cost 19.50

Bill Amount Rs. 1827756.00

Date of Inspection 30-04-14

Observation and Conclusion

the above said work - Improvements of Drains at bagalgunte Main Road left side in Ward (14) has been shown by the Concerned AE.

the above said work has been inspected along with Concerned AE.

the Measurements has been checked by me and it is found Satisfactory.

G.M.MUNIYAPPA,
B.E.(ELECT),
EXECUTIVE ENGINEER(RTD),
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073.

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike.
Dasarahalli Zone, Bangalore-73

Improvements of Drains at bagalagunte Main road Left Side in Ward No 14, Daasrahalli Sub Div

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರು
ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073.

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanaga
Dasarahalli Zone, Banga

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಪಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
- 560 073,

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara
Dasarahalli Zone, Bangalo

Improvements of Drains at bagalagunte Main road Left Side in Ward No 14, Daasrahalli Sub Div

B-R-No 335 Dt 31-8-2013



Index

S.S.M. Drain with Cover Slab

Verified

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073.

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara
Dasarahalli Zone, Bangalore